

Non-Compliant Samples

| School | Sample | Sample Location | Area | Lead (Pb) Analytical Result (ppb) | 1st Draw Spl- 1, 2nd Draw (30 sec flush)-2 | Action Item |
|--------|--------|-----------------|--|-----------------------------------|--|-------------------------------|
| JeNeir | E03A | Room 101 | Counter-Sink | 46.6 | 1 | Bilingual sign |
| | E03B | Room 101 | Counter | 12.7 | 2 | |
| | E04A | Room 101 | Washroom | 10.2 | 1 | Bilingual sign |
| | E04B | Room 101 | Washroom | undetectable | 2 | |
| | E05A | Room 102 | Counter-Sink | 34.6 | 1 | Bilingual sign |
| | E05B | Room 102 | Counter | 7.7 | 2 | |
| | E06A | Room 103 | Counter-Sink | 21 | 1 | Bilingual sign |
| | E06B | Room 103 | Counter | 11 | 2 | |
| | E10A | Pod 2 | Corridor Entry water fountain on right | 5.5 | 1 | Out of Service w/poss removal |
| | E10B | Pod 2 | Corridor Entry water fountain on right | 5.04 | 2 | |

| | | | | | | |
|------|-------|--------------|----------------|------|---|-------------------------------|
| MJHS | JH01A | Gym-North | | 7.61 | 1 | Out of Service w/poss removal |
| | JH01B | Gym-North | | 47.6 | 2 | |
| | JH7B | Pre-K | Entry Corridor | 12.3 | 2 | Remove |
| | JH08A | Room 304 | | 9.69 | 1 | Bilingual Sign |
| | JH08B | Room 304 | | 9.6 | 2 | |
| | JH09A | Room 306 | Sink | 14.3 | 1 | Bilingual Sign |
| | JH09B | Room 306 | | 14.6 | 2 | |
| | JH11A | Room 307 | Wash Station | 8.37 | 1 | Remove |
| | JH11B | Room 307 | | 6.41 | 1 | Remove |
| | JH11C | Room 307 | | 8.45 | 1 | Remove |
| | JH11D | Room 307 | | 14.8 | 2 | Remove |
| | JH12A | Nurse Office | Counter | 38 | 1 | Bilingual sign |
| | JH13A | Nurse Office | Washroom | 6.11 | 2 | Bilingual sign |
| | JH14A | Cafe | Fountain | 16 | 1 | Replacing with Water Cooler |
| | JH14B | Cafe | | 8.84 | 2 | Replacing with Water Cooler |